



Annex I:



filter cartridge of insufficient quality



high quality filter cartridge

Annex II:

filter cartridge of insufficient quality
due to distorted axial support profiles

